

02/29/2024

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
R40001	Drive Lane (Red)	2004	Mercury	Sable	GY	UNK		3.0
	Transmission/Drive Train: Road Test; Steering System: Needs Repair, Needs Wheel Bearings							
R40002	Drive Lane (Red)	2003	Ford	Focus	BG	56459		2.0
	Transmission/Drive Train: Road Test							
R40003	Drive Lane (Red)	1999	Buick	Century	SI	126850		3.1
	Transmission/Drive Train: Road Test							
R40004	Drive Lane (Red)	2009	Nissan	Rogue	BZ	102264		2.5
	Transmission/Drive Train: Road Test							
R40005	Drive Lane (Red)	2006	Chevrolet	Colorado	SI	134468		2.5
	Engine Runner: Runs Rough; Transmission/Drive Train: Yard Driven Only; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Electrical System: Needs Repair; Battery							
R40007	Drive Lane (Red)	2006	Chevrolet	Trailblazer	BK	192564		4.2
	Electrical System: ABS Light On, Traction Control Light On, Gas Tank Strap Broken - strapped up							
R40008	Drive Lane (Red)	2004	Volkswagen	Jetta	GY	223493		1.8
	Transmission/Drive Train: Road Test; Steering System: Needs Repair, Needs Wheel Bearings							
R40009	Drive Lane (Red)	2008	Honda	Odyssey	BK	151205		3.5
	Transmission/Drive Train: Road Test; Electrical System: Needs Repair; Battery							
R40010	Drive Lane (Red)	2006	Honda	Accord	SI	171783		3.0
	Transmission/Drive Train: Road Test							
R40011	Drive Lane (Red)	2006	Chevrolet	Equinox	PR	183348		3.4
	Rockers Rusty							
R40012	Drive Lane (Red)	2010	Jeep	Patriot	TA			2.0
	Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots, front subframe has rust hole							
R40013	Drive Lane (Red)	2003	Acura	TL	GY	189596		3.2
	Transmission/Drive Train: Transmission Problem, Does Not Go Into Gear, Yard Driven Only; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged							
R40014	Drive Lane (Red)	2006	Honda	Civic	BR	192071		1.8
	Suspension System: Needs Stabilizer Links; Electrical System: ABS Light On, bumper damaged							

R40015	Drive Lane (Red)	2009	Hyundai	Santa Fe	SI	206514	2.7
	Transmission/Drive Train: Road Test; Electrical System: Check/Service Engine Light On						
R40016	Drive Lane (Red)	2004	Ford	Ranger	TA	143523	3.0
	Rear Window Broken, Tailgate Handle Broken						
R40017	Drive Lane (Red)	2009	Saturn	Vue	BK	156042	3.6
	Transmission/Drive Train: Road Test						
R40018	Drive Lane (Red)	2008	Ford	Taurus	BL	279022	3.5
	Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Needs Stabilizer Links; Steering System: Needs Repair, Needs Ball Joints; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, SRS/Airbag Light On, Check/Service Engine Light On						
R40019	Drive Lane (Red)	2012	Ford	Transit Connect	WH	184481	2.0
	Frame/Unibody: Needs Repair Due to:, Rocker Panels Rusted Thru						
R40020	Drive Lane (Red)	2016	Dodge	Journey	BK	2.4	
	Transmission/Drive Train: Road Test						
R40021	Drive Lane (Red)	2006	Ford	F150	WH	164287	4.6
	Transmission/Drive Train: Road Test, 4x4 Not-Working; Electrical System: Needs Repair, Check/Service Engine Light On						
R40022	Drive Lane (Red)	2011	Cadillac	DTS	WH	160461	4.6
	Cooling System: Needs Repair, Leak at Head Gasket; Transmission/Drive Train: Road Test; Electrical System: Needs Repair, Check/Service Engine Light On						
R40023	Drive Lane (Red)	2008	Honda	Civic	GY	134716	1.8
	Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Needs Stabilizer Links; Options: A/C Does Not Work (blows warm)						
R40024	Drive Lane (Red)	2005	Ford	Escape	RD	166268	3.0
	Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged, Tailpipe, Needs Hangers/Clamps, Muffler; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots						
R40201	Cert Repair (Red) No Guarantee/As Is	2011	Subaru	Outback	RD	1633032	3.6
	Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, Brake System/ Brake Line Leaks; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots						
R40202	Cert Repair (Red) No Guarantee/As Is	2008	Ford	Focus	BL	163360	2.0
	Engine Non-runner: Unable to Test; Electrical System: Needs Repair; Electrical System : Wiring Damaged; Electrical System: Check/Service Engine Light On						
R40204	Cert Repair (Red) No Guarantee/As Is	2002	Toyota	Camry	GO	161843	3.0
	Engine Non-runner: Unable to Test; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Electrical System: Needs Repair; Electrical System : Wiring Damaged						
R40205	Drive Lane (Red)	2014	Jeep	Grand Cherokee	BK	241201	3.6
	Engine Runner: Runs Rough; Cooling System: Needs Repair, Radiator Leaks; Transmission/Drive Train: Transmission Problem, Does Not Go Into Gear, Yard Driven Only; Brake System:Needs Repair, ABS Light On; Electrical System: Needs Repair; Electrical System : Wiring Damaged; Battery						
R40206	Cert Repair (Red) No Guarantee/As Is	2011	Ford	E Series Van	WH	244084	5.4
	Transmission/Drive Train: Transmission Problem, Does Not Go Into Gear						

R40207	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test; Electrical System: Needs Repair; Battery	2007	Honda	Civic	BK	222288	1.8
R40208	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test; Electrical System: Needs Repair; Electrical System : Wiring Damaged; Battery	2004	BMW	Convertible	SI	181791	3.0
R40209	Cert Repair (Red) No Guarantee/As Is Brake System: ABS Light On; Electrical System: Check/Service Engine Light On	2005	Dodge	Caravan	BL	89684	3.3
R40210	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test	2015	Chevrolet	Equinox	GY	187798	2.4