



Contract Holder

INTERNET ONLY

Partnering with

Sale!

North East
Pennsylvania
auto auction inc.

860 North Keyser Avenue

Scranton, PA 18504

1.888.282.2606 or 570.207.CARS

www.nepautoauction.com

THIS IS AN INTERNET BUS AND TRUCK SALE ONLY!

OPEN FOR INSPECTION MONDAY - FRIDAY 8:00 AM TIL 4:00 PM

Open to public, businesses and dealers!

Sale begins at 12:00 pm EST on Wednesday, June 02, 2021
and final bidding is scheduled to close around 11:00 am EST
on Wednesday, June 09, 2021

*****BID - BUY ONLY AT autoauctions.gsa.gov**

Payment is to be made before 12:30 pm EST on Friday,
June 11, 2021 or you will be in default to the Federal Government



Vehicles can be pulled from the sale for federal use, so check the
<https://autoauctions.gsa.gov> website for changes



GSA OnBlock Sale Day Catalog

Total Vehicles: 16
(Printing 1 - 16)

Run#	Lane#	Aut. WO/SN	Photo	Year	Make	Model	VIN	Mileage	Equipment	Announced Conditions	Scheduled Sale Date	Summary
1	G	382263		2009	FORD	F350SD	1FDWF37R89EA03397	29,148	8D-AT-AC-PS-PB-EW-DL-CC-CD-HT-4x4-TL	<ul style="list-style-type: none"> BUMPER & RUNNING BOARD DAMAGE RUST Hail damage 	06/09/2021	
2	G	374758		2010	BLUE BIRD	SCHOOL BUS / TR	1BABNBXA4AF273620	97,594	6D-AT-AC-PS-ABS-CD-HT-RWD	<ul style="list-style-type: none"> Inop - not driveable RUST 	06/09/2021	
3	G	380314		2012	IC CORPORA	3000	4DRAMAAN9CB420935 -		6D-AT-AC-PS-ABS-CC-HT-RWD	<ul style="list-style-type: none"> DOES NOT START OR DRIVE Mechanical condition unknown NO KEYS - HEAVY RUST INOPERABLE 	06/09/2021	
4	G	383436		2013	FORD	F750	3FRNF7FC4DV796797	42,247	6D-AT-PB-VI-CD-HT-RWD-SAB	<ul style="list-style-type: none"> CARGO BOX DAMAGE SCRATCHES RUST 	06/09/2021	
5	G	378804		2009	INTERNATIO	4000	1HTJTSKM59H059666	11,906	8D-AT-AC-PB-CC-HT-RWD	<ul style="list-style-type: none"> 14 foot flatbed/ composite floor RUST PAINT FADED & PEELING 	06/09/2021	
6	G	382266		2009	INTERNATIO	4000	1HTMMAAM49H068509	48,490	6D-AT-VI-FM-HT-RWD	<ul style="list-style-type: none"> FUEL TANK & FILTER WERE REPLACED TRUCK DOES NOT START RUST-PAINT PEELING- WHEELS WERE PAINTED HOLES IN CARGO BOX & DENTS 	06/09/2021	
7	G	382265		2009	INTERNATIO	4000	1HTMMAAMX9H068515	28,496	6D-AT-HT-RWD	<ul style="list-style-type: none"> RUST HOLES FORMING IN CARGO BOX 	06/09/2021	
8	G	382264		2009	FORD	F750	3FRNF75E99V204837	25,239	6D-AT-PS-PB-VI-HT-RWD-TL-SAB	<ul style="list-style-type: none"> BRAKES FUNCTION PROPERLY - PARKING BRAKE WORKS BRAKES BROKEN - BRAI LIGHT ON RUST -PAINT PEELING-RUST ON WHEEL HEAVY FRAME & UNDERCARRIAGE RUST 	6/09/2021	

Run#	Lane#	Auc. WO:SN	Photo	Year	Make	Model	VIN	Mileage	Equipment	Announced Conditions	Scheduled Sale Date	Summary
9	G	380099		1996	TRAILMOBIL	VAN TRAILER	1PT071AE2T9009763	-	AT-HT-RWD	<ul style="list-style-type: none"> SOME HOLES HEAVY RUST HEAVY UNDERCARRIAGE RUST 	06/09/2021	
10	G	380098		1994	TRAILMOBIL	VAN TRAILER	1PT071AE7R9006348	-	HT-RWD	<ul style="list-style-type: none"> BRAKES INOPERABLE HEAVY UNDERCARRIAGE RUST HEAVY RUST 	06/09/2021	
11	G	371506		2010	INTERNATIO	4000	1HTMMAAM8AH188916	32,712	6D-AT-VI-HT-RWD	<ul style="list-style-type: none"> FRAME RUST RUST -RUST ON WHEELS SEAT TORN TILT BED 	06/09/2021	
12	G	374891		2009	INTERNATIO	4000	1HTJTSKMX9H060019	65,516	8D-AT-PB-VI-FM-HT-RWD	<ul style="list-style-type: none"> RUST -FRONT SEAT TORN CARGO AREA CHIPPED 20 foot STEEL FLATBED LIFTGATE CARGO BOX HAS HOLES 	06/09/2021	
13	G	374872		2008	INTERNATIO	4000	1HTJTSKM48H632863	87,931	8D-AT-AC-PS-PB-HT-RWD	<ul style="list-style-type: none"> RUST -CARGO BOX FLOOR BUCKLED EMISSIONS WARNING LIGHT ON 16 FOOT BED LENGTH SCRATCHES-PEELING-DENTS 	06/09/2021	
14	G	371505		2008	INTERNATIO	7000	1HTWAAAR88J641237	17,676	6D-AT-VI-AM-HT-RWD	<ul style="list-style-type: none"> SEVERE RUST RUST ON FRAME Dump body Snow plow stored in bed SEVERE CARGO BOX DAMAGE 	06/09/2021	
15	G	374890		2008	INTERNATIO	4000	1HTMMAAL38H645066	36,683	6D-6S-VI-FM-HT-RWD	<ul style="list-style-type: none"> 18 foot bed length Rust on undercarriage Paint peeling on cab RUST -FRAME RUST -FRONT SEAT TORN Manual transmission Air brakes 	06/09/2021	
16	G	374873		2008	INTERNATIO	4000	1HTMMAAL48H632925	68,609	6D-AT-PB-VI-HT-RWD	<ul style="list-style-type: none"> RUST - FRAMI RUST Bed length- 18 feet FRONT SEAT TORN 	06/09/2021	